

Westport Crescent 115ft









The Westport Crescent 115ft "Columbus," formally known as "Life of Riley", was sold in July 2021 to an experienced New Zealand yachtsman, who made some basic improvements, provisioned the vessel, left San Diego, and sailed over 7,500 nautical miles to her new home in NZ. In the next year, the Owner spent one million dollars on a large number of upgrades and improvements - which are detailed in the many sections of the narrative of this listing; in the many photographs of this listing, one can see the extensive selection of tenders and toys and the many improvements in the outside spaces of "COLUMBUS," including the boat deck and the aft "beach club." Even before this extensive Refit in New Zealand, the vessel underwent a major refit at the DELTA shipyard in Seattle, and the DELTA yard in Sidney, British Columbia, as well as the CRESCENT shipyard, in Vancouver, BC, where she was originally built.

General

Year: 1994

Price: US\$4,450,000 Additional Charges: Plus GST & Duty

Boat Type: Power

Hull Type: Displacement Motoryacht

Location:

Engine/Fuel:

Hull Material:

Auckland

Diesel

GRP

Dimensions

Engines

Length: 115 ft No. of Engines: Two

LOA: 115 ft Engine Brand: MTU 8V396TE94

 Beam:
 24ft
 Engine(s) HP:
 1502 hp

 Draft:
 6.5ft
 Hours:
 2619

Builder / Designer

Tankage

Builder: Westport Fuel: 7,150 gal
Designer: Jack Sarin Water: 840 gal

Holding: 300 gal
Other Details: 300 gal

Accommodations

• SUN LOUNGE - The main deck is accessed from either the port or starboard side entry doors or an entry door forward from the cockpit. Features include a bar with a refrigerator, ice maker, and a breakfast nook settee that seats six around a beautifully crafted, hydraulically operated hi/lo teak dining table and deck. A polished stainless steel spiral staircase to the port leads to the boat deck. One of the unique features of the sun lounge is the outward opening and sliding glass windows around the perimeter, giving a fresh air environment. • SALON - Separated from the sun lounge by electric glass doors, which operate automatically by a motion sensor or manually pressing an activation button. Like the sun lounge, the salon has four sliding windows allowing fresh air to cross ventilation. The salon is extremely spacious, taking advantage of the entire width of the generous 24' beam. The salon is designed with a formal dining area in the forward section, a game table centre, and a comfortable lounge area featuring an entertainment centre in the aft portion. This different salon area is beautifully highlighted by the tasteful use of teak and bevelled glass, illuminated cabinetry, indirect soft lighting, and inset lighting details. One ocustomgna res of this custom on the yacht is tsoffitflective ceiling soffit, whose design compliments the graceful contours of the cabinetry. Forward of the entertainment centre is a games table that seats four and cabinetry featuring built-in surround sound speakers for the television. • **DINING AREA** - Beautihighlightg table seats eight comfortably for formal dining with custom crafted teak table with golden maple racetrack inlays. Ample storage is provided around and table in teak and bevelled glass-fronted buffets. This passthrough is closed off by mirrored teak doors. • GALLEY - Accessed either from the entry door inboard of the starboard companionway, immediately forward of the day, or head from the main port deck entry door. This allows the entire entry to have discreet entries, b, be closed off from the remainder of the vessel, an,d not d, disturb the owner and guests. The galley is equipped with large commercial refrigeration units and has treme storage space, two deep appliance garages, all upgraded appliances, and a large U-shaped countertop. • POWDER ROOM - Located off the starboard companionway (On Deck Day Head) • MAIN SUITE - At the forward end of the companionway, a centralised bed is located

Galley

• LiebhrearaRearigeFatt&r/Dkeezebullivia dirbingner tablecti@aptainge cabangueasuiteefulahead & slasmeng Overwecktionow/2/decotren•Okievheeaid & slasmeng Overwecktionow/2/decotren•Okievheeaid & slasmengaborrealbegreatorishesede
Diispewase•KoospeoliekidReanigagetorishesede
BlueteinDfateseahew/CostomerGiadritecsinkasko
Decibeteidropetsiderevalley idoorfoorganleyc&•
starteeceansty Area

Helm Station Equipment • Furuno NavPilot 700 autopilot • Furuno AIS • Furuno colour sounder w/swim step transducer (2014) • Naiad stabilizer control panel (2014) • Kahlenberg quint triple air horns • ZF Electronic controls for main engines and transmissions (2014) • Two Stidd chairs • Chart Light • 5 Chart drawers • Furuno color sonar (2014) • ICOM M604 VHF radio (2014) • ICOM M602Radio • Wesmar bow thruster controls • Wesmar stern thruster controls • ACR electronics RCL-600 spotlight controls (6 million candle power) • 3 Windshield Wipers with controls (2014) • Overhead red lights • TSH 1330C- Maritron fuel tank level, engine temp gauges, fuel flow meter, water level, water maker remote & wind info • TZT BB 19" 19" Furuno Hatteland touch screens (3) • 12" Furuno screens (2) • Furuno RD33 multigauge - position, air & water temp, speed (2014) (2) • Radar - RCH-014 stand alone • FLIR night vision camera • Nobeltc charting software Wing Stations and Boat Deck Docking **Control Stations**

(2) Vesithearck tet 0000 hrwate incomme teol (2) Westhean bow thightse40dowtr34phasse electeratorso(1stats of 20014) 4 0/2/16 philoture in letter to 10/2/23 ulmiocariscans (0/e/41/e/1) Montheradvistors 2000xv13Spathedsite General Booxes 647006stratterrs aus p.E.41/2012A Anteaisc a 180 (de Sp (2004 15) • ENeltr Stati iconenveert (£005) of KOV Helytiz) i (£0545) Controben 20 ation politicion de Sarbphone (20 1 ations hratvenmetvo im Stattova plVsMacn55@ssadardheykteem fortch bodrevstep & diAgrii / 2006 Sed-bei atuli xTcM angers seconitorio de no arateras E ærtho iste aposo co (120) lætely conclupit Batteeridesokith? Date Textes recordity entires Battleoiles - Biligreepu greninstanto lotattis riens a Battle sies -Mantervioly prametoring gainel scentifical Macethronis. Alyts teprot l'Aghatsf Carto me consulte it a Dessero Foileeus trautinon enlarion anothermenotes metal passeed Newslome tastrolis. Matieresystiteen VATCUI sattestyn padietig Nietko 8758 Be tightistier countrols • AC/DC substation electrical panels

The fibreglass hull is cored using an AIREX foam core. Construction includes two layers of HYDREX resin-impregnated, closed cell 3/4" AIREX on the bottom, each layer being separated by solid fibreglass. The hull sides, deck & superstructure are constructed using 1" of HYDREX resin-impregnated closed cell coring. The hull bottom has a barrier coat. Below waterline stripped back to glass 2 x bond coats, 2 x primer coats, 2.5 coats Antifoul. (IMO antifouling certificate) Thrusters, Props stripped back, and two coats of prop speed. Stern anchor – removed anchor and chain and blanked off. Anodes replaced and added shaft keyway anodes.

• (A21) MeTULE-V28 PGETES 24 i (4) 5 05 2 throw 1 g hro Dri (42 0 11 4) • Engines: Blostser Widealers with 1510 hepotout blosts in 2002 a6470000dtooTuesnc@uwwe775lhpovYramaahoa 40/20 Altacu666a19S266t9uhesu550S04CDPavAtprit2202191e of Raeptatoined telefolier infrestotransandiusted valves, • estentible esternique esterniqu Dyssitelien Aon Chrainss v&/5000h& v7/000heathra Ba U Aeroc Kair Wearsks & Cibaent Coloroter, Hoyothasible Sow & Stern Umalestereter H.yglnası (1200 il.) Odd iyolga 8 iyotlelarte heisve Engineersoom, Maih Etegine Pote Stategee, 7,150 GallobapilFukedciess Faholts&w@foledfiniesFuvealteransfer Soyastednow if ibe who stee is by & teorath decigle of all twater Washtotonsorf on Eleckripit, Hylphotra Licito A Entry Stylestem for ivew of ultrapst fold bodie typest / Bo dexthaus to . Stiegine Rocho Dian SystePlate/ElopoipPowdedi Coptader • Wileite afts a (2001/5t) a (201i) iz eEr 8 HRBn (20165) of 201. • (2014) O(21)s Bleacula basin sw/on b, o tv t&rbydgithd guell of b ry a za fety BWHestriabilis filteripotenen BBQQ@ntr Dlectace um Chooncomessed of 50° RPNWardO admoss sed of 50° Epoperción r 10 250 01 (2270 1200) • 1 B detendres pectral (2270 1210) • Suppostpoor 1 20500 Bull Mile the knightness t 3820 GdP and s for OpesoenMarcetsgines - Full Service Pensek Oil / Fuel fuel filter / Turbo inspection/gearbox oil / raw water pump service Seawater lines replaced Hydraulics replaced the steering ram Hydraulics stab port ram replaced

21' Boston Whaler tender LED Interior light fixtures throughout (2014) Water Maker (2014) Rebuild and recover helm seat (2014) Install fridges, icemakers, and wine fridge teak front panels Install a new motor on the compressor air Install new microwave Install rod holders Replace holding tank check valves Rebed windows Install leather on the dash - pilothouse Paint foredeck Supply pilot house steering wheel Install new deck shower cockpit Install Maritron fuel flow meters Install Maritron engine gauges and tank monitoring High water switches Water pumps Install ZF electronic controls - all stations (5) Install Datum controls for Naiad with 16 sq.ft.fins - stabilizers Upgrade electronics Install two Stidd helm chairs Replace fridges in the sunroom and wheelhouse Haul boat in Vancouver - service bottom Replace cutlass bearings Service rudders Service thrusters Install N2K transducer Service all running gear as necessary Soundproof engine room Install Walker air system Replace hot water tanks, clean out the complete water system

Saterlige Watenplumdpisiereplade all Saterline Dismentet (1718) bled iggers deserritionen hydrane II aste lat GLA extellateclesos esirlo etadlit Somers Sevoitabet cotaillew for SolsAdbiSAssalltahidervoetoveleghtsyscharia easihter Setellite arrodnoed rated netro (5/5) so Istata V Tvsca trellite bolderrenoicattinenstervretedad litvestad litratdisumnid-ship Repetamenta Batek kpdeokingun cozotkonits & sterli ite unge windo Syspherodresstadm baaldarhastanlice all XaphoanietryastsommalmustaaelvAlphsoyrsesnas edle and coertiooanks Reditace at a taxin Equipment In stradis \and a taxin Equipment In strategy \and a taxin Equipment jos stalic pos cept stree ele lical é aunto la cito la cito la come trotan ks Sharitsefor Oldexliens Ibistal butters Danit peakees-Brostedtrade a kedrostal PSeth Blesse Senya then d pværtiscropekeln strattattrativi i i i i i i i i i i i savstemstal Appeler Install Sidentine rhoga Atea items cameras in 3 locations Feed cameras to primary pilothouse monitors Install a Swan Camera Qualplexor to allow all cameras to be viewed on one "4 box" screen Integrate Flir camera Hatteland 15t21 High Bright TouchScreen Monitor 19" (3 each) TZT Black Box control HD11 High-Definition Dome Trac Vision HD11 w/IP antenna control unit Wiring to add Galaxy Latin America to all TV locations 3 Voice lines, 2 data lines up to 134k Install all new navigation lights and wire to accommodate Two Furuno keypads Nobeltec system Dual input shore cord The option allows for the connection of two single or three-phase shore cords to the input of the Atlas system. Marine LED lighting for the entire interior of the boat Replace the air conditioning system digital control pads TWLC Multi-Unit chiller control system All new Head Hunter toilets ZFM Electronic Controls at all stations Atlas shore power electrical converter (60 or 50 hertz) (2015)

Exclusions

Artwork? antiques? all personal gear? loose items? galley gear? CD's? charts? fishing equipment? tools? spare parts? supplies & items not specifically listed on the equipment list specifications sheet.

Bridge Equipment

Gentheentobritchoptes PCG Majoheow Tinalt zenroptleteNew Apple Aimitsawasxrehrevovietula Galrevery Islem pholaienengine loungo chatroled4@evilainatemcanteDowtaelseseowieeddiDChe Onboa proceeding to Maketeroreplasementepliable edne ME Einit. Panel replace batteries Epirb recoded Columbus Generator monitoring from the Maretron system in the bridge

OCTO servic paint i paint I ancho Repla replac Repla hatche straine Whale

Canva

Add ons/ Replacements

Aft cleat added swim deck rails added with swim ladder and fairlead New bridge aft rails New Foredeck hatch Freezer Stbd compressor overhaul Freezer Port compressor overhaul New induction hob fitted New Water maker fitted Water maker manifold new Water maker 1 – full overhaul service Plumbing new water supply and sink installed New water maker station beach S/S The crew Fridge cooling pump replaced The freezer cooling pump replaced Compressor Breather fitted Cat1 completed and changed over to Cooks Flag/Registry Lift rafts serviced STBD Main engine water pump (in the process of replacement or rebuilding, awaiting quote) Oil system overhaul Crane Pricing (awaiting a quote to replace) Lights - replace 85% of exterior lights with new LED soft white lights Fuel Spinner service Black Tanks Sensor replaced FWD Fuel Tank Sensor replaced

The Company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the vessel's condition. A buyer should instruct his agents or surveyors to investigate such details as the buyer desires validated. Hours listed may vary from actual hours due to recent use. Purchaser is encouraged to verify hours before purchase. This vessel is offered subject to prior sale, price change, or withdrawal without notice.

Additional Images

























































